



ST. JOHN'S
International Airport Authority

For Immediate Release

Media Statement

For Thursday, February 26, 2015

An incident occurred at 7:30 a.m. today resulting in a CargoJet B757-200 aircraft colliding with the General Service Building, located on the Torbay Road side of the airport. The building has been evacuated for safety reasons while the incident and the damage are being investigated.

There were two crew members on board the aircraft and no injuries were sustained by those on board the aircraft or in the building.

The St. John's International Airport Authority's Emergency Response team is on site, and the Transportation Safety Board and the RNC have been notified.

Flight operations are not impacted as a result of this incident.

Media Contact:

Sara Norris
Marketing and Communications Advisor
St. John's International Airport Authority
709-758-8756, 709-725-3460
snorris@stjohnsairport.com
www.stjohnsairport.com